Work Orde July-12-12 12:3.		· 1		*87	281*						Page 1
Revision ID:	D4018-5 Rib			Accept	*N900	0401	ი ი,	k s	etup Start Stop		S1* S2*
Start Date: Required Date: Reference:		Start Qty: 8.00 Req'd Qty: 8.00	*8* *8*		Cust Item II Customer:	D :					
Approvals:		MLJ	Date: 12 07	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		te:	Acc	K	Run Start Stop	171	R1* R2*
Sequence ID/ Work Center II		Operation Ecscription		Set Up/ Run Hours	Tool ID	Tool# P		Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revisi	on Nbr									
D4018	С									<u> </u>	
*100 *100* Large Fab Large Fab			e as per dwg D4018 nd remove identification n	0.00 0.00 narkings	-	321			SS	_ <i>13</i> ·	0 <i>1· 3</i> 2
*110 * 1 * QC . Quality Control	C	QC6- Inspect dimensio	ns to drawing	0.00	4 13.1.22		چ	3			
120 *120* Packaging	I	Identify as per dwg & S Memo	Stock Location:WAO	0.00		527			[]	3.61.	22_
Packaging											

												DQA:	Date:	·			
NCR:	Yes	/ No					WORK ORDER NON-O	COI	VFOR	AANCE / UPE	DATE	OA Closed:	Data				
						1			QA Closed: Date:								
Nork Order: DISPOSITION									AGAINST DEPARTMENT/PROCESS								
Part No.						Rework Scrap Use-as-is		Skid-tube Crosstube Machining Small Fab Thorm of a main a			4	Water Jet d. Eng. Coor. re/Packaging	Engineering Quality Other				
NCR	No.			-			Work Order Update		Thermoforming Finishing Large Fab Composite			i necystor	Supplier	J Other			
Root					Desc	rip	tion of work order update	1	nitial	Act	ion	Sign &					
Cause		Date	Step	Qty		0	r Non-conformance	Ch	ief Eng	Descr	iption	Date	Verification	QC Inspector			
oc/Data			}														
quip/Tooling																	
perator	_											·					
1aterial	_																
etup	<u> </u>																
ther	<u> </u>													,			
rocess								ŀ									
upplier	<u> </u>																
raining	ļ																
napproved							_	<u> </u>									
1								AUL	T CATE	50'RY							
Landi	ng (1			Г	_	General	_	11.			1	r	7			
	_	Bending			., <u> </u>		Bend		Grain		<u> </u>	Ovalized	. –	Pressure/Forced			
	\vdash	Centre No	t Concer	itric to U	" ⁵	$\overline{}$	BOM/Route	<u> </u>	Hardwa			Over/Under		Temperature/Cure			
	<u> </u>	Cracks	~ .		-	_	Broken/Damaged	<u> </u>	i	on Incomplete		Part Incorred	—	Weld			
	_	Crushed/0	rimpea.			-	Burrs	_	1	oris Incomplete/U	Inclear	Part Lost/Mi	ssing	Wrong Stock Pulled			
	Cuffs						Contamination		Mainte		<u> </u>	Part Moved					
							Countersink	_	Mislabe		<u> </u>	Positioned V		7			
							Cut Too Short	<u> </u>	Misread		L.	Power Loss/	Surge	Other			
	\vdash	Ripples in			-		Drill Holes	<u> </u>	Offset					***			
	_	Torque W		xtrusion	<u> </u>		Drawing		Out of C	alibration				· -			
	1	Turning Se	equence			ı	Finish	1	Out of S	ermence							

Outside Dimensions

Wave/Twist in Tube

Folio

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G

Work Orde July-12-12 12:3								Page 2				
Item ID: Revision ID: Item Name:	D4018-:	5		Accept	*N900	040	100	*	Setup	Start Stop		S1* S2*
Start Date: 7/10/12 Start Qty: 8.00 Required Date: 8/17/12 Req'd Qty: 8.00 Reference:			*8* *8*		Cust Item I Customer:			G:				
Approvals: Process Plan: QC:		s Plan:	Date:	Tooling: SPC (Y/N):	D _i			Run	Start Stop		R1* R2*	
Sequence ID/ Work Center II	D	Operation Description OC21- Final Inspection	- Work Order Release	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	t Re Qt	•	Reject Number	Insp. Stamp
130 QC		Memo		0.00						3/1	123	90

Quality Control

13/1/23 90 MF 23 13-1-23

											DQA:	Date:	
NCR:	Yes	/ No				WORK ORDER NON-O	CON	IFORI	MANCE / UP	DATE			
											QA Closed	: Date:	
Work Orde	er:					DISPOSITION			AGAINST DE	PARTMENT	PROCESS		
Part No.						Rework Scrap		Skid-tube Crosstube Machining Small Fab			-	Water Jet od. Eng. Coor.	Engineering Quality
NCR No.						Use-as-is Work Order Update				Finishing Composite	Rec/Sto	re/Packaging Supplier	Other
Root					Descri	ption of work order update	I	nitial	Ac	tion	Sign &		
Cause		Date	Step	Qty	(or Non-conformance	Ch	ief Eng	Desc	ription	Date	Verification	QC Inspector
Doc/Data													
Equip/Tooling													
Operator			1										
Material													
Setup													
Other	\Box												
Process													:
Supplier													
Training													
Unapproved	П												
				•		F	AUL	T CATE	GORY		.1	_ -	
Landi	ng G	iear				General							····
		Bending				Bend		Grain			Ovalized		Pressure/Forced
	Centre Not Concentric to O/S				BOM/Route		Hardwa	re	Over/Under tolerance Temperature				

			· ·		•	, ,
	·	Cracks	Broken/Damaged	Inspection Incomplete	Part Incorrect	Weld
		Crushed/Crimped.	Burrs	Instructions Incomplete/Unclear	Part Lost/Missing	Wrong Stock Pulled
		Cuffs	Contamination	Maintenance	Part Moved	•
		Heat Treat	Countersink	Mislabeled	Positioned Wrong	
		Inspection Strip in Tube	Cut Too Short	Misread	Power Loss/Surge	Other
		Ripples in Bend	Drill Holes	Offset	•	
		Torque Waves in Extrusion	Drawing	Out of Calibration		
		Turning Sequence	Finish	Out of Sequence	1.20.	
		Wave/Twist in Tube	Folio	Outside Dimensions		
/FORMS /Ou	alieu	Assurance and OA (NCDMO Paul				•

Page 1

Work Order ID:

87281

Parent Item:

D4018-5

Parent Item Name:

Rib

Start Date: 7/10/12

Required Date: 8/17/12

Start Qty: 8.00

Required Qty: 8.00

Comments:

IPP RevA: new issue DD 09.11.26 verified by:EC

IPP Rev:B as per dwg revA 10.03.15

verified by:EC IPP Rev:C as per dwg RevB DD 10.04.16 verified by:EC Rev:D as per dwg revC DD 10.08.18 verified by:EC

IPP

	Rev.D as per awg	CVC DD 10.06.	o verme	J UY.LC									
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M304TS0.500W.049		Purchased	No			100	f	542.8963	0.5558	4.6804211			

Square Tubing

Location	Loc Qty	Loc Code
MAT034	542.8962523	
118460	0.00001534	
121328	2.059994	
121565	22.964943	
121808	517.8713	

										DQA:	Date:		
NCR:	Yes / N	o			WORK ORDER NON-	100	NFOR	MANCE / UP	DATE				
										QA Closed:	Date:		
Work Ord	er.	DISPOSITION AGAINST DEPARTMENT/PROCESS											
WOIR OIG	C1.				Rework	٦		Skid-tube	Crosstube	1	Water Jet	Engineering	
Part I	No.				Scrap	1		Machining	Small Fab	Pro	d. Eng. Coor.	Quality	
					Use-as-is	1	l .	noforming	Finishing	4	re/Packaging	Other	
NCR I	No.				Work Order Update	1		Large Fab	Composite	1	Supplier	1 1	
						-			-	_			
Root				Descri	ption of work order update	1	nitial	Act	tion	Sign &			
Cause	Dat	e Step	Qty	(or Non-conformance	Ch	ief Eng	Desc	ription	Date	Verification	QC Inspector	
Doc/Data		İ			•								
Equip/Tooling													
Operator													
Material						1							
Setup													
Other													
Process													
Supplier													
Training]									
Unapproved													
					F	AUL	T CATE	GORY					
Landi	ng Gear				General		-			_		_	
	Bendi	ng			Bend		Grain			Ovalized		Pressure/Forced	
Centre Not Concentric to O/S					BOM/Route		Hardwa	re		Over/Under	tolerance	Temperature/Cure	
CracksBroken/I					Broken/Damaged		Inspecti	on Incomplete		Part Incorre	ct	Weld	
	Crushed/Crimped_				Burrs		Instruct	ions Incomplete/	Unclear	Part Lost/M	issing	Wrong Stock Pulled	
	Cuffs				Contamination		Mainte	nance		Part Moved		_	
	Heat 7	reat			Countersink	Г	Mislahe	lod		Positioned Wrong			

Misread

Out of Calibration

Out of Sequence

Outside Dimensions

Offset

Power Loss/Surge

Other

Turning Sequence

Wave/Twist in Tube

Ripples in Bend

Inspection Strip in Tube

Torque Waves in Extrusion

Cut Too Short

Drill Holes

Drawing

Finish

Folio

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G







